



1




Turn all Servo Motor to 90 degree


2




3




4




5




6




7




8




9




10









11




12









19




21




23



20



22



24

Flat Head M3x14mm

